




PMD3XT Wiring Schematic Examples:




P1 - Power and Digital Controls




P2 - Dual Mechanical Relay Outputs



P4 - Analog Output



P5 - DC Signal Input (LPPS Series Potentiometer)



P5 - DC Signal Input (ILPS Series Inductive Sensor)

